

FIG. 1




FIG. 2






FIG. 3





Drain Side Program Rate Distribution After UV Erase




Fig. 6

Source Side Program Rate Distribution After UV Erase




FIG 7




FIG 8




Fig. 9